

## Read Me

# MIDI I/O

This Read Me covers installation, compatibility information, and known issues for using the Digidesign MIDI I/O on both Mac OS 9 and Mac OS X.

---

## MIDI I/O Installer

The MIDI I/O Installer can be used on Mac OS 9 and Mac OS X. It will automatically install the appropriate components for each operating system. For example, running the MIDI I/O Installer on Mac OS 9 will install Mac OS 9 driver components only. To install the Mac OS X driver components, restart your computer in Mac OS X and run the installer again.

### Installer Contents

The Installer contains the MIDI I/O Driver v1.5 for Mac OS 9 and the MIDI I/O Driver v2.0.3 for Mac OS X.


### Switching Between Mac OS 9 and Mac OS X

If you are planning to use the MIDI I/O on both Mac OS 9 and Mac OS X, you will have to install the new drivers on both operating systems. Older versions of the Mac OS 9 drivers (such as v1.0.1 and v1.0) will no longer work once your MIDI I/O unit has been set up for use in Mac OS X. Running the MIDI I/O Installer application on Mac OS 9 ensures installation of the required v1.5 drivers.

---

## Mac OS X Firmware Update

MIDI I/O requires a firmware update to function properly on Mac OS X. Refer to the Firmware Updater Read Me (in Applications/Digidesign/Documentation/MIDI IO) for instructions on using the MIDI I/O Firmware Updater application.

 *Be sure to copy the MIDI I/O Firmware Updater application to your hard drive. The MIDI I/O Firmware Updater application may crash if you attempt to run it from the CD or from a network server.*

---

## Mac OS 9 Firmware Update

If the MIDI I/O firmware version is incompatible with the updated Mac OS 9 driver, the new USB driver extension will automatically proceed with loading new firmware into MIDI I/O. This process starts only when connecting MIDI I/O for the first time after installing the new driver. A firmware update in progress is shown on MIDI I/O by the front panel LEDs flashing in sequence from left to right. Once new firmware is loaded, all LEDs will start to blink in an alternating fashion. You now have to reboot (or disconnect and reconnect MIDI I/O) for the driver to load and work properly.

If you have updated the MIDI I/O firmware on Mac OS X already, the Mac OS 9 driver will load and work without requiring additional firmware updates.

---

## Known Issues (Mac OS 9 Only)

### USB Power Dialog

If you connect multiple MIDI I/O units and exceed the USB power limitation for your computer, you may encounter a warning dialog for each MIDI I/O unit attached. Click OK in all dialogs and restore power to MIDI I/O or any active USB hubs as necessary.

### Hot-Plug Limitation

OMS Studio Setup will recognize a “hot-plugged” MIDI I/O interface only if you have previously declared it in OMS Studio Setup. (A hot-plugged interface is one that you have connected to a USB port *after* your computer or OMS has already started up.) MIDI interfaces that you have not previously declared in OMS Studio Setup cannot be hot-plugged. They will be recognized only after you quit and relaunch the OMS Studio Setup application. As a general rule, you should quit OMS Studio Setup before connecting any new MIDI I/O interfaces.

### Rescanning For Missing Interfaces

When launching OMS, you will encounter a warning dialog if OMS cannot find all of the declared MIDI I/O interfaces in the currently active Studio Setup document. You can click the Re-Scan button to update your setup but only *after* the internal firmware of MIDI I/O has been fully loaded. Always allow five to ten seconds after connecting MIDI I/O for the initialization process to complete before you click Re-Scan. The graphics contained within this warning dialog may occasionally display incorrectly during launch of Pro Tools. This will not affect system performance.