DAE 5.1.1cs6 Update (For Windows 2000) Read Me

Fix for Pro Tools TDM Windows systems using a 1622 Interface

Aug. 14, 2001

What is addressed?

Preliminary testing has shown that this interim DAE release can be used to address the following problem with Pro Tools 5.1.1 TDM Windows systems:

Using a 1622 Interface on the core TDM card generates "DAE error -7101".

Who Should Use this Update?

This update should be used by any 5.1.1 TDM Windows user with a 1622 interface installed on the core card. If you do not have a 1622 you do not need to use this DAE.dll (version 5.1.1.67). This problem does not occur with other interfaces. DAE.dll (version 5.1.1.67) does not provide any additional functionality beyond the features of the DAE.dll (v5.1.1.66) that shipped with Pro Tools v5.1.1.

Installation notes:

This is not an auto installer. The download consists of DAE.dll (version 5.1.1.67) and this Read Me only.

To install:

1. Close all active applications
2. Double click to open "my computer" (on the desktop). Open C: boot drive partition.
3. Open "program files">"Digidesign">, view "Pro Tools" folder.
4. Drag and drop the DAE.dll (version 5.1.1.67) file over the "Pro Tools" folder and release it. Allow it to overwrite existing files.
5. Close folders and restart computer.

Digidesign Customer Service