

### DAE/DIO 5.0.1cs3 Update (For Macintosh)

#### For Audiomedia III – Fixes Static on Left Channel

#### What's Addressed?

Preliminary testing has shown that this interim release that can be used with Pro Tools 5.0.1 ToolBox systems to address the following problem:

- Crackling audio in the left channel output of some Audiomedia III cards. (The erroneous audio is not part of the recorded audio files)

#### Who Should Use this Update?

This update should be used by any Audiomedia III /Toolbox customers who are using DAE/DIO v5.0.1 and experiencing this problem. If you are not experiencing this problem with your system, you should not install these components. Older versions of DAE/DIO are unaffected by this bug.

#### Installation Notes:

This is not an auto-installer. This download consists of DAE<sup>a</sup> 5.0.1cs3, Digidesign™ Direct I/O 5.0.1cs3, and this Read Me only. To install:

- 1) Open the DAE Folder (startup drive/System Folder).
- 2) Remove the old DAE<sup>a</sup> app (trash it, or move it to another folder on the drive).
- 3) Move the new DAE<sup>a</sup> into the DAE Folder.
- 4) Close the DAE Folder.
- 5) Open the Extensions folder (startup drive/System Folder).
- 6) Remove the old Digidesign™ Direct I/O extension.
- 7) Move the new Digidesign™ Direct I/O extension into the Extensions folder.
- 8) Close the Extensions Folder and then the System Folder.
- 9) Restart the computer.

#### Further Questions?

If you have any questions or comments, please contact us via our website:

<http://www.digidesign.com>