

DigiSystem INIT 5.1.3cs5 Update

(DigiSystem INIT for Pro Tools|24 MIX Macintosh Systems Only)

Fixes included with DigiSystem INIT 5.1.3cs5:

- Pro Tools MIX cards not recognized in late Model Digidesign 7-slot, SBS 7-slot, and SBS 13-slot Chassis.

Because this update contains only the DigiSystem INIT, it does not provide the fixes found in other Pro Tools 5.1.3 updates (cs1, cs2, and so on.). DigiSystem INIT 5.1.3cs5 may be used in conjunction with any version of the Pro Tools 5.1.1 or 5.1.3 application, but should only be used if your MIX cards are not being recognized by the chassis listed above.

What's Fixed in DigiSystem INIT 5.1.3cs5?

DigiSystem INIT 5.1.3cs5 contains the following:

Fixed: Pro Tools MIX Cards Not Recognized in Late Model Digidesign 7-slot, SBS 7-slot, and SBS 13-slot Chassis

The following chassis, shipped after January 2002, did not recognize Pro Tools|24 MIX cards when installed. This problem has been fixed. In addition, Pro Tools|24 MIX and Pro Tools|HD users will need to download an updated version of DigiTest (available soon) if they wish to test their setups with these chassis.

- Digidesign 7-slot chassis
- SBS 7-slot chassis
- SBS 13-slot chassis

DigiSystem INIT 5.1.3cs5 is still compatible with earlier chassis.

Who Should Use This Update?

DigiSystem INIT 5.1.3cs5 can only be used to replace the Pro Tools 5.1.1 or 5.1.3 DigiSystem INIT. If you are using an earlier version of Pro Tools, you must first upgrade to Pro Tools 5.1.1 or 5.1.3, then install DigiSystem INIT 5.1.3cs5. Contact Customer Support for upgrade information.

This update should be used only by:

- Any Pro Tools 5.1.1 or 5.1.3 user with a Digidesign 7-slot, SBS 7-slot or SBS 13-slot chassis shipped after January 2002


⚠ Important: We recommend that only the Pro Tools users specified above use this update. DigiSystem INIT 5.1.3cs5 is provided as an interim "customer support (CS)" release to address the issues described. While our testing has not shown these changes introduce other problems, this version has not been fully qualified by Digidesign.

Updating the DigiSystem INIT

To use this fix, you'll need to replace your existing versions of the DigiSystem INIT application.

To replace the DigiSystem INIT:

- 1 Drag the new DigiSystem INIT into the Extensions folder within your System folder.
- 2 Click OK to replace the older version. (Should you need to revert to the "older" version, simply run the Pro Tools 5.1.1 or 5.1.3 installer.)

 *Going forward, newer "customer support" versions of Pro Tools components may be made available to provide additional bug fixes. When available, these versions will be located on the Download page in the Support section of Digidesign's Web site (located at www.digidesign.com).*